Site Reference: 54

Area: Platt House, Dairy Lane, Chainhurst

Physical and social	Located close/within the existing settlement of Chainhurst but not to the village of Marden
connectivity	Limited bus service
Highway considerations	Access via Dairy Lane – would require upgrading depending on proposed use/number of dwellings Dairy Lane, very narrow mostly single track lane
Character and setting	Within Dairy Lane and surrounded by other dwellings albeit sporadic. Significant local visual impact but limited impact on long views. Potential impact on Reed Place Farmhouse, a grade II listed building to the north of the site
Fluvial and surface water	Not within Flood Zones 2 or 3 but Chainhurst is on higher ground and can be cut off Surface water flooding occurred in recent weeks
Ecological considerations	No designations Ecological Constraint Level 3 (boundary may house protected/notable species) KCC Archaeology interested in site at previous Call for Sites
Education and health	2.5 miles from Marden – limited public transport, not suitable for walking
Employment	2.5miles from Marden – limited public transport, not suitable for walking Broadband speed very low
Retail and leisure	2.5 miles from Marden – limited public transport, not suitable for walking
Other	Rejected in MBC Strategic Housing and Economic Land Availability Assessment 2016 (Ref HO35) "Established B1 Industrial Estate" refers to a few existing outbuildings (B1) in a farmyard.

Conclusions	Not suitable for housing owing to unsustainable location and scale of development
	Not suitable for B1 use owing to limited road/transport links

Site Reference: 123

Area: Dairy Field, Chainhurst

Physical and social	Located to the south of the existing settlement of Chainhurst but not to the village of Marden.
connectivity	Limited bus service.
Highway considerations	Access on Hunton Road. No safe pedestrian access.
Character and setting	Local visual impact but limited overall on long views
Fluvial and surface water	Not within Flood Zones 2 or 3 but Chainhurst is on higher ground and can be cut off Surface water flooding occurred in recent weeks
Ecological considerations	No designations
Education and health	2.5 miles from Marden – limited public transport, not suitable for walking
Employment	2.5miles from Marden – limited public transport, not suitable for walking
Retail and leisure	2.5 miles from Marden – limited public transport, not suitable for walking
Other	Should be considered in conjunction with site referenced 213 Prospect House
Conclusions	Not suitable for housing owing to unsustainable location

Site Reference: 213

Area: Prospect House, Hunton Road, Chainhurst

Physical and social	Located to the south of the existing settlement of Chainhurst but not to the village of Marden.
connectivity	Limited bus service
Highway considerations	Access on Hunton Road
	No safe pedestrian access
	Close to a bend – unsuitable sight lines
Character and setting	Local visual impact but limited overall on long views
Fluvial and surface water	Not within Flood Zones 3 but access in Flood Zone 2. Chainhurst is on higher ground and can be cut off Surface water flooding occurred in recent weeks (add photos)
Ecological considerations	No designations
Education and health	2.5 miles from Marden – limited public transport, not suitable for walking
Employment	2.5miles from Marden – limited public transport, not suitable for walking
Retail and leisure	2.5 miles from Marden – limited public transport, not suitable for walking
Other	If suitable should come forward with 123 Dairy Field
	Poor sight lines identified in MBC Strategic Housing and Economic Land Availability Assessment 2016 (Ref HO84)
Conclusions	Not suitable for housing owing to unsustainable location

Site Reference: 304

Area: Land east of Hunton Road, adj to 1 Rainham Villas, Chainhurst

Physical and social	Located to the north of the existing settlement of Chainhurst but not to the village of Marden
connectivity	Limited bus service.
Highway considerations	Access on Hunton Road
	No safe pedestrian access
Character and setting	Local visual impact but limited overall on long views. Potential impact on Chainhurst Farm a grade II* listed building and associated grade II listed barns located to the north
Fluvial and surface water	Not within Flood Zones 2 or 3 but Chainhurst is on higher ground and can be cut off Surface water flooding occurred in recent weeks
Ecological considerations	No designations
Education and health	2.5 miles from Marden – limited public transport, not suitable for walking
Employment	2.5miles from Marden – limited public transport, not suitable for walking
Retail and leisure	2.5 miles from Marden – limited public transport, not suitable for walking
Other	
Conclusions	Not suitable for housing owing to unsustainable location and setting of nearby listed buildings